





CLAIM REPORT		EARLY CHECKING	
Claim Number	: ACCU-CLPP-PLG-2210001	Claim Date	: 19 October 22
Customer	: arif alfarisy	Phone/Email	: 082379049190
Plate Number	: BG 8474 CT	Car Type	: AUDI A6
Battery Type	: (Amaron/Pro Rider) - Pro Rider ETZ5S	Loaned Battery	: (Amaron/Hi Life Pro) - DIN 45LBH
EARLY BATTERY TEST			
Voltage : 89.90	CCA : 78.43	Starting : 24.34	Charging : 32.43
EARLY DIAGNOSTIC		CLAIM EVIDENCE	
<div>1. Starting problem 2. Charging Problem 3. Current Leakage 4. Forgot to turn off the vehicle electricity 5. Loose or dirty battery fastener</div>		<div></div>	
Submitted By,		Received By,	
<div></div>		Super Admin	