



Two signals (RClk and 160MHzClk) are nor longer present on new HDI  
Tf. they are not routed on the new adapter card  
So we terminate them here (60 Ohms would match the connector saver cable's impedance).



Adapter to use new module-to-DTB adapter with old HDI		
University of Nebraska-Lincoln		
File: CableAdapter.sch		
Sheet: /		
Title: Cable Adapter		
Size: A4	Date: 2 may 2014	Rev: 1
KiCad E.D.A.		Id: 1/1