



**SCOPE OF ACCREDITATION TO ISO/IEC 17025:2017  
AND  
ANSI/NCSL Z540-1-1994 (R2002)  
ANSI/NCSL Z540.3-2006 (R2013)**

**Keysight Technologies, Inc. Service Center**

10090 Foothills Blvd.  
Roseville, CA 95747  
Scott Arrants 916-788-5540  
scott\_arrants@keysight.com www.keysight.com

**CALIBRATION**

Valid to: **November 16, 2024**

Certificate Number: **AC-1498**

**Satellite locations in:**

- [El Segundo, CA \(AC-1498.01\)](#)
- [Colorado Springs, CO \(AC-1498.02\)](#)
- [Richardson, TX \(AC-1498.04\)](#)
- [Tempe, AZ \(AC-1498.05\)](#)
- [West Valley City, UT \(AC-1498.06\)](#)
- [Arlington Heights, IL \(AC-1498.07\)](#)
- [Fort Wayne, IN \(AC-1498.08\)](#)
- [Bethlehem, PA \(AC-1498.09\)](#)
- [Nashua, NH \(AC-1498.10\)](#)
- [Montreal, QC Canada \(AC-1498.11\)](#)
- [Mississauga, ON Canada \(AC-1498.12\)](#)
- [Tlaquepaque, JL Mexico \(AC-1498.13\)](#)
- [Barueri, SP Brazil \(AC-1498.14\)](#)
- [Plantation, FL \(AC-1498.16\)](#)
- [Redmond, WA \(AC-1498.17\)](#)
- [Greensboro, NC \(AC-1498.18\)](#)
- [Calgary, AB Canada \(AC-1498.19\)](#)
- [Kimballton, IA \(AC-1498.20\)](#)
- [Elk Horn, IA \(AC-1498.20\)](#)
- [Ottawa, ON Canada \(AC-1498.21\)](#)