



- Configuration as of 2020/03/22
- Radios: 4x Ubiquiti airMax training system radio units
 - Radios present as Rocket XM, but bullet firmware needed
 - AREDN FW aredn-3.19.3.0-ubnt-bullet-m
- Antennas: 4x Ubiquiti antennas as shipped with airMax training system
- RF chamber: Tescom A5901C-00
- Various dummy loads
- VLAN such that control laptop can reach all devices, but devices do not DTD link
- Concurrent communication tests between Radios A-B and C-D
- Tests performed with iperf3 run from radios
 - Both directions run concurrently
 - UDP, controlled bandwidth, zero copy
 - iperf3 -c \${host} -t5 -Z -u -b\${speed}m -J -O1
- 10MHz channels