



- Ferrite Bead for accelerometer
- TVS diode protection
- ~~motor protection, flyback wheel~~
- ~~mosfet reverse diode for batterie connector~~
- ~~connect all the pins~~
- ~~check for 0805 components~~



open hardware

<http://diodes.com/datasheets/ZCCT1009.pdf>  
<https://www.sparkfun.com/datasheets/OpenServo/openservo.pdf>  
<http://www.analog.com/media/en/technical-documentation/data-sheets/ADXL337.pdf>

<https://www.allaboutcircuits.com/technical-articles/choosing-and-using-ferrite-beads/>