




EDP |E| Field Plot - Full Period




EDP |E| Field FFT - Full Period




EDP |E| Field Plot - 1/4 Period




EDP |E| Field FFT - 1/4 Period




EDP |E| Field Plot - 2/4 Period




EDP $|E|$ Field FFT - 2/4 Period




EDP |E| Field Plot - 3/4 Period




EDP |E| Field FFT - 3/4 Period




EDP |E| Field Plot - 4/4 Period




EDP $|E|$ Field FFT - 4/4 Period




EDP Ex Field Plot - Full Period




EDP Ex Field FFT - Full Period




EDP Ex Field Plot - 1/4 Period




EDP Ex Field FFT - 1/4 Period




EDP Ex Field Plot - 2/4 Period




EDP Ex Field FFT - 2/4 Period




EDP Ex Field Plot - 3/4 Period




EDP Ex Field FFT - 3/4 Period




EDP Ex Field Plot - 4/4 Period




EDP Ex Field FFT - 4/4 Period




EDP Ey Field Plot - Full Period




EDP Ey Field FFT - Full Period




EDP Ey Field Plot - 1/4 Period




EDP Ey Field FFT - 1/4 Period




EDP Ey Field Plot - 2/4 Period




EDP Ey Field FFT - 2/4 Period




EDP Ey Field Plot - 3/4 Period




EDP Ey Field FFT - 3/4 Period




EDP Ey Field Plot - 4/4 Period




EDP Ey Field FFT - 4/4 Period




EDP Ez Field Plot - Full Period




EDP Ez Field FFT - Full Period




EDP Ez Field Plot - 1/4 Period




EDP Ez Field FFT - 1/4 Period




EDP Ez Field Plot - 2/4 Period




EDP Ez Field FFT - 2/4 Period




EDP Ez Field Plot - 3/4 Period



EDP Ez Field FFT - 3/4 Period



EDP Ez Field Plot - 4/4 Period



EDP Ez Field FFT - 4/4 Period

