





1. Table of Contents (This Page)  
Created on Thu Feb 27 16:42:57 2014


2. bottom
3. top-gnd
4. outline
5. plated-drill
6. unplated-drill
7. componentmask
8. soldermask
9. topsilk
10. bottomsilk
11. toppaste
12. topassembly
13. bottomassembly
14. fab



































There are 3 different drill sizes used in this layout, 251 holes total

| Symbol | Diam. (Inch) | Count | Plated? |
|--------|--------------|-------|---------|
| Y      | 0.012        | 237   | YES     |
| +      | 0.038        | 10    | YES     |
| x      | 0.126        | 4     | NO      |

Title: (unknown) - Fabrication Drawing

Author: Andreas Rosvall

Date: Thu Feb 27 15:42:57 2014 UTC



Board outline is the centerline of this path