

# DATA VISUALIZATION USING MINITAB

Pie Chart of Shift







Chart of Flaws




Histogram of Torque




Run Chart of Filter



Cause-and-Effect Diagram



Probability Plot of Hours



## DATA MODELING

Data Modeling is the process of creating a data model for an information system by applying certain techniques.

IPE – 314

QUALITY MANAGEMENT  
SESSIONAL

SUBMITTED TO  
A.P. TANMOY DAS

SUBMITTED BY  
MD.SHAQUIT HOSSAIN  
TAMIM

ROLL: 201636021

RUN CHART RADONTEST.MTW ***				
	C1	C2	C3	C4
	Filter	Membrane	Open Cup	Badge
1	26	21	36	21
2	21	33	34	23
3	16	26	33	27
4	28	46	29	29
5	27	25	30	24
6	19	32	36	26
7	21	33	28	27
8	26	22	34	26
9	25	30	34	24
10	16	26	33	25
11	20	37	33	31