



QUOTATION

Phone #

Toll Free #

Customer Name

LFO INC

Year

2006

Make

FORD

Model

FOCUS

Last 6 VIN

123565

Mileage

91,097

Service Advisor

Phone No. 1

Phone No. 2

QUANTITY	DETAILS OF RECOMMENDED REPAIRS	LABOR	PARTS	OTHER
	MSI:-			
	REPAIR STEERING COLUMN -	350.00		
	REPLACE LEFT LOWER BALL JOINT	100.00	215.00	
	REPLACE FRONT STABILIZER BAR	75.00	235.00	
	REPLACE LEFT SIDEVIEW MIRROR	75.00	185.00	
	REPLACE DRIVE SHAFT AND CENTER BEARING	75.00	900.00	
	MACHINE FRONT BRAKE ROTORS	75.00		
	REPLACE WIPER BLADES		35.00	
	OTHERS:- ELECTRIC FUEL PUMP -NOISY			
	WINDOW RATTLES IN DOOR WHEN DOWN			
	Subtotal	750.00	1,570.00	-
	Estimated Shop Supplies			
	Total Estimate	2,320.00		
	Estimated Tax	94.20		
	Total	2,414.20		

The above estimate is based on our inspection and does not include any additional parts or labor which may be required after the work has been started. Occasionally after the repair has started, damaged or broken parts are discovered which are not evident on initial inspection. Estimate prices subject to change after 30 days. Not responsible for any delays caused by unavailability of parts or delays in parts shipment by supplier or transporter. All terms and conditions of repair orders and invoices apply (copy available upon request).