




1. Table of Contents (This Page)






Created on Sun Jun 28 21:52:48 2020


2. top
3. ground
4. outline
5. plated-drill
6. unplated-drill
7. componentmask
8. soldermask
9. topsilk
10. bottomsilk
11. toppaste
12. bottompaste
13. topassembly
14. bottomassembly
15. fab






































R5 C6
R4
R3
R2
R1
C5
C4
C3
C2
C1
S1
S2
C10












There are 7 different drill sizes used in this layout, 186 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.020	26	YES
+	0.020	2	YES
x	0.028	54	YES
o	0.053	14	YES
□	0.091	2	YES
▽	0.094	4	NO
⊕	0.126	4	NO

Title: (unknown) - Fabrication Drawing
Author: Miroslav Sladek
Date: Sun Jun 28 19:52:48 2020 UTC



Board outline is the centerline of this path