


1st plan (21 actions):
 (grab-device)
 (flip top bottom)
 (place-device)
 (pick-tool star-sd power)
 (unscrew-power-non-stuck pcb-s4 star-sd bottom)
 (put-away-tool star-sd power)
 (pick-tool flat-sd power)
 (unscrew-power-non-stuck pcb-s0 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s1 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s2 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s3 flat-sd bottom)
 (put-away-tool flat-sd power)
 (grab-device)
 (pick-tool cutter scara)
 (cut-connector motor-axis pcb bottom)
 (place-device)
 (put-away-tool cutter scara)
 (pick-tool pliers power)
 (assert-clear pcb)
 (extract-with-pliers-high-confidence pcb pcb-a4 bottom)
 (check-removed pcb bottom)

2nd plan (19 actions):
 (grab-device)
 (flip top bottom)
 (pick-tool cutter scara)
 (cut-connector motor-axis pcb bottom)
 (place-device)
 (put-away-tool cutter scara)
 (pick-tool star-sd power)
 (unscrew-power-non-stuck pcb-s4 star-sd bottom)
 (put-away-tool star-sd power)
 (pick-tool flat-sd power)
 (unscrew-power-non-stuck pcb-s0 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s1 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s2 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s3 flat-sd bottom)
 (put-away-tool flat-sd power)
 (pick-tool pliers power)
 (assert-clear pcb)
 (extract-with-pliers-high-confidence pcb pcb-a4 bottom)
 (check-removed pcb bottom)



3rd plan (17 actions):
 (grab-device)
 (flip top bottom)
 (pick-tool cutter scara)
 (cut-connector motor-axis pcb bottom)
 (place-device)
 (put-away-tool cutter scara)
 (pick-tool star-sd power)
 (unscrew-power-non-stuck pcb-s4 star-sd bottom)
 (put-away-tool star-sd power)
 (pick-tool flat-sd power)
 (unscrew-power-non-stuck pcb-s0 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s1 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s2 flat-sd bottom)
 (unscrew-power-non-stuck pcb-s3 flat-sd bottom)
 (assert-clear pcb)
 (lever-power-high-confidence pcb pcb-a3 bottom)
 (check-removed pcb bottom)

4th plan (13 actions):
 (grab-device)
 (flip top bottom)
 (pick-tool cutter scara)
 (cut-connector motor-axis pcb bottom)
 (put-away-tool cutter scara)
 (place-device)
 (pick-tool hammer power)
 (bash pcb bottom)
 (put-away-tool hammer power)
 (pick-tool pliers power)
 (assert-clear pcb)
 (extract-with-pliers-high-confidence pcb pcb-a4 bottom)
 (check-removed pcb bottom)