





Use jumper to connect I2C pins to A4/A5 or mega I2C pins when dedicated pins missing




3V3 boost circuit (through hole option)




3V3 boost circuit (surface mount option)




Temperature sensor



5V boost circuit



Onboard ADC



Title: FLC100_shield_v1.0

Version: 1.0

2012-08-29 22:05:25

Drawn By: Steve Marple

1/1