













phase shift = 180

4.54V

11.11V

phase shift = 183.6

phase diff = 3.6

inverting because it has phase shift

6.16V

12.22V

phase difference = 0

non- inverting because no phase shift

4.7V

1.5V

0V

13.8653

13.958

13.958

-13.958

13.8635

13.958

-13.958

-13.958

13.8626