



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 07/03/2021 to 13/03/2021 (WEEK-2)

Message No: 402

Date : 05/03/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 06/03/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	41	19:00	-	03:00	BHUU	33	J11	113	12:00	-	20:00
	2	E12	70	05:00	-	13:00		34	J12	104	00:45	-	08:45
	3	E13	61	04:15	-	12:15		35	J13	81	20:00	-	04:00
	4	E14	56	00:30	-	08:30		36	J14	112	04:00	-	12:00
	5	E15	60	11:00	-	19:00		37	J15	128	12:15	-	20:15
	6	E16	41	00:30	-	08:30		38	J16	120	20:15	-	04:15
JUNAGADH	7	F11	17	22:00	-	06:00		39	J17	142	04:45	-	12:45
	8	F12	27	04:30	-	12:30		40	J18	148	00:15	-	08:15
	9	F13	22	20:00	-	04:00	RAJKOT	41	R11	86	12:00	-	20:00
	10	F14	21	11:15	-	19:15		42	R12	56	22:45	-	06:45
	11	F15	21	04:30	-	12:30		43	R13	78	04:00	-	12:00
	12	F16	28	20:15	-	04:15		44	R14	70	20:00	-	04:00
AMRELI	13	G11	73	19:00	-	03:00		45	R15	73	12:15	-	20:15
	14	G12	90	11:00	-	19:00		46	R16	35	00:15	-	08:15
	15	G13	96	11:30	-	19:30		47	R17	65	04:30	-	12:30
	16	G14	60	00:00	-	08:00		48	R18	29	20:15	-	04:15
	17	G15	93	08:00	-	16:00	PORBANDAR	49	V11	28	20:45	-	04:45
	18	G16	74	20:30	-	04:30		50	V12	37	06:15	-	14:15
JAMNAGAR	19	H11	46	20:00	-	04:00		51	V13	22	22:30	-	06:30
	20	H12	60	11:45	-	19:45		52	V14	47	12:15	-	20:15
	21	H13	75	04:30	-	12:30	BOTAD	53	B11	24	23:00	-	07:00
	22	H14	58	00:00	-	08:00		54	B12	30	04:15	-	12:15
	23	H15	68	12:45	-	20:45		55	B13	30	20:00	-	04:00
	24	H16	55	00:45	-	08:45		56	B14	48	12:00	-	20:00
SURENDRANAGAR	25	I11	69	05:00	-	13:00	MORBI	57	M11	47	12:15	-	20:15
	26	I12	71	00:45	-	08:45		58	M12	29	23:00	-	07:00
	27	I13	76	12:30	-	20:30		59	M13	19	20:15	-	04:15
	28	I14	60	20:30	-	04:30		60	M14	38	05:00	-	13:00
	29	I15	56	04:00	-	12:00		61	M15	71	20:15	-	04:15
	30	I16	48	23:00	-	07:00		62	M16	80	11:00	-	19:00
	31	I17	37	22:00	-	06:00		63	M17	73	23:00	-	07:00
	32	I18	46	12:30	-	20:30		64	M18	100	04:15	-	12:15



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period:07/03/2021 to 13/03/2021 (WEEK-2)

Message No: 402

Date : 05/03/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 06/03/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	42	12:45	-	20:45	AMRELI KSY	19	GK11	43	12:45	-	20:45
	2	FK12	36	12:45	-	20:45		20	GK12	45	05:15	-	13:15
	3	FK13	43	09:15	-	17:15		21	GK15	17	09:15	-	17:15
	4	FK14	37	05:15	-	13:15		22	GK16	19	05:15	-	13:15
	5	FK15	43	09:15	-	17:15	JAMNAGAR KSY	23	HK11	22	12:45	-	20:45
	6	FK16	33	05:15	-	13:15		24	HK12	21	05:15	-	13:15
SURENDRANAGAR KSY	7	IK11	13	05:15	-	13:15		25	HK15	20	09:15	-	17:15
	8	IK12	10	12:45	-	20:45	BHAVNAGAR KSY	26	HK16	22	05:15	-	13:15
	9	IK13	9	09:15	-	17:15		27	EK11	19	12:45	-	20:45
	10	IK14	9	09:15	-	17:15	BOTAD KSY	28	EK12	23	09:15	-	17:15
	11	IK15	7	05:15	-	13:15		29	BK11	22	12:45	-	20:45
	12	IK16	4	12:45	-	20:45		30	BK12	32	09:15	-	17:15
MORBI KSY	13	MK11	16	12:45	-	20:45	KUTCH KSY	31	JK11	23	12:45	-	20:45
	14	MK12	21	09:15	-	17:15		32	JK12	24	05:15	-	13:15
RAJKOT KSY	15	RK11	19	05:15	-	13:15		33	JK15	10	09:15	-	17:15
	16	RK12	15	12:45	-	20:45		34	JK16	7	05:15	-	13:15
	17	RK15	7	12:45	-	20:45	PORBANDAR KSY	35	VK11	16	12:45	-	20:45
	18	RK16	7	09:15	-	17:15		36	VK12	18	09:15	-	17:15
								37	VK15	18	05:15	-	13:15
								38	VK16	15	09:15	-	17:15

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.