



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 14/03/2021 to 20/03/2021 (WEEK-3)

Message No: 445

Date : 12/03/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 13/03/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	42	11:00	-	19:00	BHUU	33	J11	102	20:00	-	04:00
	2	E12	69	00:30	-	08:30		34	J12	94	04:00	-	12:00
	3	E13	60	00:30	-	08:30		35	J13	72	12:00	-	20:00
	4	E14	64	04:15	-	12:15		36	J14	100	00:45	-	08:45
	5	E15	62	19:00	-	03:00		37	J15	119	20:15	-	04:15
	6	E16	47	05:00	-	13:00		38	J16	116	12:15	-	20:15
JUNAGADH	7	F11	19	04:30	-	12:30		39	J17	128	00:15	-	08:15
	8	F12	24	22:00	-	06:00		40	J18	138	04:45	-	12:45
	9	F13	24	11:15	-	19:15	RAJKOT	41	R11	73	20:00	-	04:00
	10	F14	22	20:00	-	04:00		42	R12	58	04:00	-	12:00
	11	F15	22	22:30	-	06:30		43	R13	63	22:45	-	06:45
	12	F16	29	12:15	-	20:15		44	R14	59	12:00	-	20:00
AMRELI	13	G11	64	11:00	-	19:00		45	R15	55	20:15	-	04:15
	14	G12	81	19:00	-	03:00		46	R16	33	04:30	-	12:30
	15	G13	80	20:30	-	04:30		47	R17	47	00:15	-	08:15
	16	G14	70	08:00	-	16:00		48	R18	22	12:15	-	20:15
	17	G15	79	00:00	-	08:00	PORBANDAR	49	V11	27	12:45	-	20:45
	18	G16	66	11:30	-	19:30		50	V12	32	00:45	-	08:45
JAMNAGAR	19	H11	33	11:45	-	19:45		51	V13	27	04:30	-	12:30
	20	H12	42	20:00	-	04:00		52	V14	41	20:15	-	04:15
	21	H13	54	00:00	-	08:00	BOTAD	53	B11	32	04:15	-	12:15
	22	H14	47	04:30	-	12:30		54	B12	33	23:00	-	07:00
	23	H15	45	20:45	-	04:45		55	B13	31	12:00	-	20:00
	24	H16	51	06:15	-	14:15		56	B14	49	20:00	-	04:00
SURENDRANAGAR	25	I11	66	00:45	-	08:45	MORBI	57	M11	41	20:15	-	04:15
	26	I12	77	05:00	-	13:00		58	M12	33	05:00	-	13:00
	27	I13	72	20:30	-	04:30		59	M13	19	12:15	-	20:15
	28	I14	69	12:30	-	20:30		60	M14	32	23:00	-	07:00
	29	I15	54	23:00	-	07:00		61	M15	75	11:00	-	19:00
	30	I16	49	04:00	-	12:00		62	M16	81	20:15	-	04:15
	31	I17	44	12:30	-	20:30		63	M17	73	04:15	-	12:15
	32	I18	38	22:00	-	06:00		64	M18	101	23:00	-	07:00



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period:14/03/2021 to 20/03/2021 (WEEK-3)

Message No: 445

Date : 12/03/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 13/03/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	43	05:15	-	13:15	AMRELI KSY	19	GK11	47	05:15	-	13:15
	2	FK12	36	05:15	-	13:15		20	GK12	36	09:15	-	17:15
	3	FK13	39	12:45	-	20:45		21	GK15	19	12:45	-	20:45
	4	FK14	36	09:15	-	17:15		22	GK16	19	09:15	-	17:15
	5	FK15	48	12:45	-	20:45	JAMNAGAR KSY	23	HK11	17	05:15	-	13:15
	6	FK16	32	09:15	-	17:15		24	HK12	15	09:15	-	17:15
SURENDRANAGAR KSY	7	IK11	12	09:15	-	17:15		25	HK15	17	12:45	-	20:45
	8	IK12	10	05:15	-	13:15	BHAVNAGAR KSY	26	HK16	17	09:15	-	17:15
	9	IK13	9	12:45	-	20:45		27	EK11	20	05:15	-	13:15
	10	IK14	8	12:45	-	20:45	BOTAD KSY	28	EK12	23	12:45	-	20:45
	11	IK15	5	09:15	-	17:15		29	BK11	26	05:15	-	13:15
	12	IK16	4	05:15	-	13:15	KUTCH KSY	30	BK12	32	12:45	-	20:45
MORBI KSY	13	MK11	14	05:15	-	13:15		31	JK11	21	05:15	-	13:15
	14	MK12	17	12:45	-	20:45		32	JK12	22	09:15	-	17:15
RAJKOT KSY	15	RK11	16	09:15	-	17:15		33	JK15	8	12:45	-	20:45
	16	RK12	15	05:15	-	13:15		34	JK16	6	09:15	-	17:15
	17	RK15	6	05:15	-	13:15	PORBANDAR KSY	35	VK11	18	05:15	-	13:15
	18	RK16	5	12:45	-	20:45		36	VK12	21	12:45	-	20:45
								37	VK15	13	09:15	-	17:15
								38	VK16	11	12:45	-	20:45

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.