



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 18/04/2021 to 24/04/2021 (WEEK-4)

Message No: 659

Date : 16/04/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 17/04/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	58	00:30	-	08:30	BHUUJ	33	J11	86	04:00	-	12:00
	2	E12	63	11:00	-	19:00		34	J12	102	20:00	-	04:00
	3	E13	52	12:00	-	20:00		35	J13	79	00:45	-	08:45
	4	E14	63	20:00	-	04:00		36	J14	99	12:00	-	20:00
	5	E15	52	05:00	-	13:00		37	J15	97	04:45	-	12:45
	6	E16	44	19:00	-	03:00		38	J16	110	00:15	-	08:15
JUNAGADH	7	F11	30	20:00	-	04:00	RAJKOT	39	J17	105	12:15	-	20:15
	8	F12	29	11:15	-	19:15		40	J18	126	20:15	-	04:15
	9	F13	39	22:00	-	06:00		41	R11	53	04:00	-	12:00
	10	F14	25	04:30	-	12:30		42	R12	65	20:00	-	04:00
	11	F15	24	12:15	-	20:15		43	R13	43	12:00	-	20:00
	12	F16	44	22:30	-	06:30		44	R14	80	22:45	-	06:45
AMRELI	13	G11	83	23:00	-	07:00	PORBANDAR	45	R15	37	04:30	-	12:30
	14	G12	71	04:15	-	12:15		46	R16	33	20:15	-	04:15
	15	G13	65	08:00	-	16:00		47	R17	31	12:15	-	20:15
	16	G14	78	20:30	-	04:30		48	R18	29	00:15	-	08:15
	17	G15	63	11:30	-	19:30		49	V11	50	00:45	-	08:45
	18	G16	76	00:00	-	08:00		50	V12	38	12:45	-	20:45
JAMNAGAR	19	H11	54	00:00	-	08:00	BOTAD	51	V13	52	20:15	-	04:15
	20	H12	35	04:30	-	12:30		52	V14	42	04:30	-	12:30
	21	H13	53	11:45	-	19:45		53	B11	26	19:00	-	03:00
	22	H14	62	20:00	-	04:00		54	B12	26	11:00	-	19:00
	23	H15	37	06:15	-	14:15		55	B13	34	00:30	-	08:30
	24	H16	60	20:45	-	04:45		56	B14	33	04:15	-	12:15
SURENDRANAGAR	25	I11	51	12:30	-	20:30	MORBI	57	M11	27	05:00	-	13:00
	26	I12	68	20:30	-	04:30		58	M12	35	20:15	-	04:15
	27	I13	49	05:00	-	13:00		59	M13	21	23:00	-	07:00
	28	I14	64	00:45	-	08:45		60	M14	26	12:15	-	20:15
	29	I15	48	12:30	-	20:30		61	M15	83	23:00	-	07:00
	30	I16	56	22:00	-	06:00		62	M16	75	04:15	-	12:15
	31	I17	47	23:00	-	07:00		63	M17	78	20:15	-	04:15
	32	I18	34	04:00	-	12:00		64	M18	93	11:00	-	19:00



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 18/04/2021 to 24/04/2021 (WEEK-4)

Message No: 659

Date : 16/04/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 17/04/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	59	13:00	-	21:00	AMRELI KSY	19	GK11	59	12:45	-	20:45
	2	FK12	55	13:00	-	21:00		20	GK12	59	05:15	-	13:15
	3	FK13	55	09:15	-	17:15		21	GK15	16	09:15	-	17:15
	4	FK14	51	05:00	-	13:00		22	GK16	16	05:15	-	13:15
	5	FK15	72	09:15	-	17:15	JAMNAGAR KSY	23	HK11	18	12:45	-	20:45
	6	FK16	48	05:00	-	13:00		24	HK12	17	05:15	-	13:15
SURENDRANAGAR KSY	7	IK11	12	05:15	-	13:15		25	HK15	21	09:15	-	17:15
	8	IK12	9	12:45	-	20:45	BHAVNAGAR KSY	26	HK16	24	05:15	-	13:15
	9	IK13	8	09:15	-	17:15		27	EK11	19	12:45	-	20:45
	10	IK14	6	09:15	-	17:15	BOTAD KSY	28	EK12	21	09:15	-	17:15
	11	IK15	5	05:15	-	13:15		29	BK11	23	12:45	-	20:45
	12	IK16	3	12:45	-	20:45		30	BK12	27	09:15	-	17:15
MORBI KSY	13	MK11	11	12:45	-	20:45	KUTCH KSY	31	JK11	20	12:45	-	20:45
	14	MK12	15	09:15	-	17:15		32	JK12	20	05:15	-	13:15
RAJKOT KSY	15	RK11	15	05:15	-	13:15		33	JK15	6	09:15	-	17:15
	16	RK12	12	12:45	-	20:45		34	JK16	5	05:15	-	13:15
	17	RK15	5	12:45	-	20:45	PORBANDAR KSY	35	VK11	24	12:45	-	20:45
	18	RK16	5	09:15	-	17:15		36	VK12	30	09:15	-	17:15
								37	VK15	19	05:15	-	13:15
								38	VK16	16	09:15	-	17:15

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.