



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 10/01/2021 to 16/01/2021 (WEEK-2)

Message No: 46

Date : 08/01/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 09/01/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	25	19:00	-	03:00	BHUUJ	33	J11	94	12:00	-	20:00
	2	E12	50	05:00	-	13:00		34	J12	107	00:45	-	08:45
	3	E13	40	04:15	-	12:15		35	J13	94	20:00	-	04:00
	4	E14	67	00:30	-	08:30		36	J14	95	04:00	-	12:00
	5	E15	52	11:00	-	19:00		37	J15	111	12:15	-	20:15
	6	E16	49	00:30	-	08:30		38	J16	142	20:15	-	04:15
JUNAGADH	7	F11	39	22:00	-	06:00		39	J17	116	04:45	-	12:45
	8	F12	25	04:30	-	12:30		40	J18	153	00:15	-	08:15
	9	F13	44	20:00	-	04:00	RAJKOT	41	R11	72	12:00	-	20:00
	10	F14	18	11:15	-	19:15		42	R12	96	01:00	-	09:00
	11	F15	19	04:30	-	12:30		43	R13	53	04:00	-	12:00
	12	F16	41	20:15	-	04:15		44	R14	114	20:00	-	04:00
AMRELI	13	G11	90	19:00	-	03:00		45	R15	43	12:15	-	20:15
	14	G12	69	09:00	-	17:00		46	R16	64	00:15	-	08:15
	15	G13	50	11:30	-	19:30		47	R17	39	04:30	-	12:30
	16	G14	94	00:00	-	08:00		48	R18	46	20:15	-	04:15
	17	G15	66	08:00	-	16:00	PORBANDAR	49	V11	72	20:45	-	04:45
	18	G16	85	20:30	-	04:30		50	V12	35	06:15	-	14:15
JAMNAGAR	19	H11	89	20:00	-	04:00		51	V13	73	22:30	-	06:30
	20	H12	52	10:30	-	18:30		52	V14	38	12:15	-	20:15
	21	H13	50	04:30	-	12:30	BOTAD	53	B11	38	01:00	-	09:00
	22	H14	100	00:00	-	08:00		54	B12	26	04:15	-	12:15
	23	H15	51	12:45	-	20:45		55	B13	51	20:00	-	04:00
	24	H16	104	00:45	-	08:45		56	B14	35	08:00	-	16:00
SURENDRANAGAR	25	I11	47	05:00	-	13:00	MORBI	57	M11	39	12:15	-	20:15
	26	I12	81	00:45	-	08:45		58	M12	47	01:15	-	09:15
	27	I13	54	12:30	-	20:30		59	M13	35	20:15	-	04:15
	28	I14	67	20:30	-	04:30		60	M14	29	05:00	-	13:00
	29	I15	40	04:00	-	12:00		61	M15	84	20:15	-	04:15
	30	I16	57	01:00	-	09:00		62	M16	78	11:00	-	19:00
	31	I17	49	22:00	-	06:00		63	M17	87	01:15	-	09:15
	32	I18	32	09:00	-	17:00		64	M18	79	04:15	-	12:15



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 10/01/2021 to 16/01/2021 (WEEK-2)

Message No: 46

Date : 08/01/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 09/01/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	50	13:00	-	21:00	AMRELI KSY	20	GK11	54	13:00	-	21:00
	2	FK12	39	13:00	-	21:00		21	GK12	54	05:00	-	13:00
	3	FK13	46	13:00	-	21:00		22	GK15	8	13:00	-	21:00
	4	FK14	44	05:00	-	13:00		23	GK16	7	05:00	-	13:00
	5	FK15	57	05:00	-	13:00	JAMNAGAR KSY	24	HK11	3	13:00	-	21:00
	6	FK16	43	05:00	-	13:00		25	HK12	4	05:00	-	13:00
SURENDRANAGAR KSY	7	IK11	4	13:00	-	21:00		26	HK15	7	13:00	-	21:00
	8	IK12	1	13:00	-	21:00	BHAVNAGAR KSY	27	HK16	11	05:00	-	13:00
	9	IK13	2	13:00	-	21:00		28	EK11	1	13:00	-	21:00
	10	IK14	2	05:00	-	13:00	BOTAD KSY	29	EK12	2	05:00	-	13:00
	11	IK15	1	05:00	-	13:00		30	BK11	5	13:00	-	21:00
	12	IK16	2	05:00	-	13:00	KUTCH KSY	31	BK12	6	05:00	-	13:00
MORBI KSY	13	MK11	2	13:00	-	21:00		32	JK11	7	13:00	-	21:00
	14	MK12	1	05:00	-	13:00		33	JK12	9	05:00	-	13:00
RAJKOT KSY	15	RK11	2	13:00	-	21:00			JK15	1	13:00	-	21:00
	16	RK12	2	05:00	-	13:00	PORBANDAR KSY	34	VK11	20	13:00	-	21:00
	17	RK15	2	13:00	-	21:00		35	VK12	26	05:00	-	13:00
	18	RK16	3	05:00	-	13:00		36	VK15	3	05:00	-	13:00
	19	RK17	2	05:00	-	13:00		37	VK16	2	13:00	-	21:00

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.