



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 17/01/2021 to 23/01/2021 (WEEK-2)

Message No: 91

Date : 15/01/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 16/01/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	42	11:00	-	19:00	BHUUJ	33	J11	110	20:00	-	04:00
	2	E12	69	00:30	-	08:30		34	J12	103	04:00	-	12:00
	3	E13	59	00:30	-	08:30		35	J13	86	12:00	-	20:00
	4	E14	52	04:15	-	12:15		36	J14	114	00:45	-	08:45
	5	E15	62	19:00	-	03:00		37	J15	125	20:15	-	04:15
	6	E16	43	05:00	-	13:00		38	J16	118	12:15	-	20:15
JUNAGADH	7	F11	22	04:30	-	12:30	RAJKOT	39	J17	137	00:15	-	08:15
	8	F12	36	22:00	-	06:00		40	J18	145	04:45	-	12:45
	9	F13	29	11:15	-	19:15		41	R11	93	20:00	-	04:00
	10	F14	29	20:00	-	04:00		42	R12	74	04:00	-	12:00
	11	F15	30	22:30	-	06:30		43	R13	87	01:00	-	09:00
	12	F16	36	12:15	-	20:15		44	R14	67	12:00	-	20:00
AMRELI	13	G11	64	09:00	-	17:00	PORBANDAR	45	R15	78	20:15	-	04:15
	14	G12	83	19:00	-	03:00		46	R16	38	04:30	-	12:30
	15	G13	94	20:30	-	04:30		47	R17	75	00:15	-	08:15
	16	G14	53	08:00	-	16:00		48	R18	31	12:15	-	20:15
	17	G15	97	00:00	-	08:00		49	V11	38	12:45	-	20:45
	18	G16	65	11:30	-	19:30		50	V12	61	00:45	-	08:45
JAMNAGAR	19	H11	50	10:30	-	18:30	BOTAD	51	V13	34	04:30	-	12:30
	20	H12	76	20:00	-	04:00		52	V14	70	20:15	-	04:15
	21	H13	98	00:00	-	08:00		53	B11	29	04:15	-	12:15
	22	H14	60	04:30	-	12:30		54	B12	34	01:00	-	09:00
	23	H15	79	20:45	-	04:45		55	B13	35	08:00	-	16:00
	24	H16	63	06:15	-	14:15		56	B14	43	20:00	-	04:00
SURENDRANAGAR	25	I11	67	00:45	-	08:45	MORBI	57	M11	44	20:15	-	04:15
	26	I12	64	05:00	-	13:00		58	M12	32	05:00	-	13:00
	27	I13	67	20:30	-	04:30		59	M13	23	12:15	-	20:15
	28	I14	54	12:30	-	20:30		60	M14	41	01:15	-	09:15
	29	I15	63	01:00	-	09:00		61	M15	70	11:00	-	19:00
	30	I16	52	04:00	-	12:00		62	M16	82	20:15	-	04:15
	31	I17	34	09:00	-	17:00		63	M17	77	04:15	-	12:15
	32	I18	43	22:00	-	06:00		64	M18	103	01:15	-	09:15



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 17/01/2021 to 23/01/2021 (WEEK-2)

Message No: 91

Date : 15/01/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 16/01/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	65	05:00	-	13:00	AMRELI KSY	19	GK11	61	05:00	-	13:00
	2	FK12	52	05:00	-	13:00		20	GK12	55	13:00	-	21:00
	3	FK13	62	05:00	-	13:00		21	GK15	15	05:00	-	13:00
	4	FK14	49	13:00	-	21:00		22	GK16	11	13:00	-	21:00
	5	FK15	62	13:00	-	21:00	JAMNAGAR KSY	23	HK11	24	05:00	-	13:00
	6	FK16	46	13:00	-	21:00		24	HK12	21	13:00	-	21:00
SURENDRANAGAR KSY	7	IK11	12	05:00	-	13:00		25	HK15	16	05:00	-	13:00
	8	IK12	10	05:00	-	13:00	BHAVNAGAR KSY	26	HK16	17	13:00	-	21:00
	9	IK13	9	05:00	-	13:00		27	EK11	18	05:00	-	13:00
	10	IK14	8	13:00	-	21:00	BOTAD KSY	28	EK12	18	13:00	-	21:00
	11	IK15	3	13:00	-	21:00		29	BK11	9	05:00	-	13:00
	12	IK16	2	13:00	-	21:00	KUTCH KSY	30	BK12	14	13:00	-	21:00
MORBI KSY	13	MK11	40	05:00	-	13:00		31	JK11	18	05:00	-	13:00
	14	MK12	5	13:00	-	21:00		32	JK12	20	13:00	-	21:00
RAJKOT KSY	15	RK11	16	05:00	-	13:00		33	JK15	0	05:00	-	13:00
	16	RK12	14	13:00	-	21:00		34	JK16	0	13:00	-	21:00
	17	RK15	10	05:00	-	13:00	PORBANDAR KSY	35	VK11	32	05:00	-	13:00
	18	RK16	8	13:00	-	21:00		36	VK12	29	13:00	-	21:00
								37	VK15	21	13:00	-	21:00
								38	VK16	19	05:00	-	13:00

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.