



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 21/02/2021 to 27/02/2021 (WEEK-4)

Message No: 309

Date : 19/02/2021

Time : 17:00 Hrs.


From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 20/02/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
BHAVNAGAR	1	E11	52	00:30	-	08:30	BHUUJ	33	J11	95	04:00	-	12:00
	2	E12	57	11:00	-	19:00		34	J12	108	20:00	-	04:00
	3	E13	48	12:00	-	20:00		35	J13	89	00:45	-	08:45
	4	E14	67	20:00	-	04:00		36	J14	101	12:00	-	20:00
	5	E15	50	05:00	-	13:00		37	J15	110	04:45	-	12:45
	6	E16	71	19:00	-	03:00		38	J16	138	00:15	-	08:15
JUNAGADH	7	F11	23	20:00	-	04:00	RAJKOT	39	J17	123	12:15	-	20:15
	8	F12	16	11:15	-	19:15		40	J18	156	20:15	-	04:15
	9	F13	24	22:00	-	06:00		41	R11	51	04:00	-	12:00
	10	F14	12	04:30	-	12:30		42	R12	78	20:00	-	04:00
	11	F15	15	12:15	-	20:15		43	R13	48	12:00	-	20:00
	12	F16	29	22:30	-	06:30		44	R14	89	22:45	-	06:45
AMRELI	13	G11	84	23:00	-	07:00	PORBANDAR	45	R15	48	04:30	-	12:30
	14	G12	70	04:15	-	12:15		46	R16	49	20:15	-	04:15
	15	G13	67	08:00	-	16:00		47	R17	42	12:15	-	20:15
	16	G14	80	20:30	-	04:30		48	R18	34	00:15	-	08:15
	17	G15	63	11:30	-	19:30		49	V11	34	00:45	-	08:45
	18	G16	85	00:00	-	08:00		50	V12	21	12:45	-	20:45
JAMNAGAR	19	H11	56	00:00	-	08:00	BOTAD	51	V13	31	20:15	-	04:15
	20	H12	36	04:30	-	12:30		52	V14	24	04:30	-	12:30
	21	H13	45	11:45	-	19:45		53	B11	31	19:00	-	03:00
	22	H14	70	20:00	-	04:00		54	B12	23	11:00	-	19:00
	23	H15	36	06:15	-	14:15		55	B13	37	00:30	-	08:30
	24	H16	64	20:45	-	04:45		56	B14	41	04:15	-	12:15
SURENDRANAGAR	25	I11	60	12:30	-	20:30	MORBI	57	M11	30	05:00	-	13:00
	26	I12	79	20:30	-	04:30		58	M12	38	20:15	-	04:15
	27	I13	59	05:00	-	13:00		59	M13	23	23:00	-	07:00
	28	I14	74	00:45	-	08:45		60	M14	29	12:15	-	20:15
	29	I15	41	12:30	-	20:30		61	M15	78	23:00	-	07:00
	30	I16	53	22:00	-	06:00		62	M16	64	04:15	-	12:15
	31	I17	45	23:00	-	07:00		63	M17	79	20:15	-	04:15
	32	I18	31	04:00	-	12:00		64	M18	84	11:00	-	19:00



# Paschim Gujarat Vij Company Limited

Load Management Unit, 400 kV sub-station campus, JETPUR  
Phone: 02823-225133 Fax: 02823-226308 Email : eelmu.pgvccl@gebmail.com

Reg. & Corporate Office, "Paschim Gujarat Vij Seva Sadan" Off, Nana Mava Road, Laxminagar, Rajkot - 360 004

CIN: U40102GJ2003SGC042908; Phone: (0281)2380425, 2380427; Fax : 2380428;

Email: info.pgvccl@gebmail.com; Web site: www.pgvccl.com



## Power Supply Schedule for Agriculture Groups

Effective Period: 21/02/2021 to 27/02/2021 (WEEK-4)

Message No: 309

Date : 19/02/2021

Time : 17:00 Hrs.

From : Executive Engineer, LMU, PGVCL, Jetpur

To : All SE(O&M/TR) / EE(O&M/TR) under PGVCL area & EE(SUB-SLDC) Jetpur

- Latest schedule and other information is available on our website [www.pgvccl.com](http://www.pgvccl.com)

Time schedule for supplying **08:00** hrs 3 phase power to Agriculture Groups of PGVCL as approved by State Load Despatch Center, Gotri, Baroda. This schedule will be effective from Saturday evening, i. e. from **19:00 Hrs of 20/02/2021**. Group timings are subject to change.

Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply			Circle / Area	No	Group	Load (MW)	Timing of 3 Phase Power Supply		
JUNAGADH KSY	1	FK11	37	05:15	-	13:15	AMRELI KSY	19	GK11	38	05:15	-	13:15
	2	FK12	30	05:15	-	13:15		20	GK12	36	09:15	-	17:15
	3	FK13	33	12:45	-	20:45		21	GK15	17	12:45	-	20:45
	4	FK14	30	09:15	-	17:15		22	GK16	17	09:15	-	17:15
	5	FK15	36	12:45	-	20:45	JAMNAGAR KSY	23	HK11	20	05:15	-	13:15
	6	FK16	27	09:15	-	17:15		24	HK12	18	09:15	-	17:15
SURENDRANAGAR KSY	7	IK11	12	09:15	-	17:15		25	HK15	17	12:45	-	20:45
	8	IK12	11	05:15	-	13:15	BHAVNAGAR KSY	26	HK16	17	09:15	-	17:15
	9	IK13	9	12:45	-	20:45		27	EK11	20	05:15	-	13:15
	10	IK14	8	12:45	-	20:45	BOTAD KSY	28	EK12	22	12:45	-	20:45
	11	IK15	7	09:15	-	17:15		29	BK11	24	05:15	-	13:15
	12	IK16	4	05:15	-	13:15	KUTCH KSY	30	BK12	31	12:45	-	20:45
MORBI KSY	13	MK11	16	05:15	-	13:15		31	JK11	22	05:15	-	13:15
	14	MK12	19	12:45	-	20:45		32	JK12	23	09:15	-	17:15
RAJKOT KSY	15	RK11	16	09:15	-	17:15		33	JK15	9	12:45	-	20:45
	16	RK12	14	05:15	-	13:15		34	JK16	6	09:15	-	17:15
	17	RK15	7	05:15	-	13:15	PORBANDAR KSY	35	VK11	12	05:15	-	13:15
	18	RK16	6	12:45	-	20:45		36	VK12	13	12:45	-	20:45
								37	VK15	11	09:15	-	17:15
								38	VK16	9	12:45	-	20:45

NOTE: (1) Please pass this message up to sub-station and sub-division level to concerned & for public display.