



## New Work Order

**Order #TVO-7000001919**

Dear Installer,

Thank you for accepting Tyres Vision Work Order #TVO-7000001919

Please find the details below :

### Customer Details

Guest

### Vehicle Information

Plate No.: F39191

Make: Gmc

Model: Sierra-1500

Year: 2008

### Installer Information

Safeer Tyres - Ajman

Al Jurf, Industrial Area - 1, Sheikh Ammar Bin

Humaid St

Ajman

United Arab Emirates

**Delivery Date/Time :** 22-10-30 12:00pm

### Order Updates

customer will come for tire fitting-- Please assist

ITEM	QTY
Windforce 285/70 R17 121/118R CatchFors AT II 2022	4

### Please note the following,

1. The tyres supplied to you under this work order must be fitted ONLY to the Vehicle bearing the license plate number and description specified here. Please contact us if the customer insists on fitting these to another vehicle.
2. Please refuse to accept delivery if the tyres being delivered by the courier are not the exact same specifications and DOT as listed here
3. The customer has paid for new tyres, delivery, installation, balancing and disposal of old tyres. You will have to charges the customer directly for Alignment or any other service you provide.
4. The work order will not be considered complete unless the customer sign this work order and you email back a scanned copy to your Tyres Vision contact.

Please feel free to call us at or Write to us at [customercare@tyresvision.com](mailto:customercare@tyresvision.com)

Job Complete (Y/N):\_\_\_\_\_

Remarks (if any):\_\_\_\_\_

Date & Time:\_\_\_\_\_

Customer Signature:\_\_\_\_\_