






*Add-on 2 push button and LED to make the debug process easier
*Make sure the power supply to the Vin do not exceed 12V



UNCONTROLLED WHEN PRINTED

	PROJECT : Job Number + Project Name		
	FILENAME : File Name		
	EDMS NO : EDMS NO	SIZE : A3	REV : 00
	DRAWN BY : PIC	DATE : Date	
APPROVED & REVIEWED BY :			SHEET 1 OF 1