



6876 - Talon
Alternate Build
Design and Instructions
by DrewG (2021)





Please give credit when modifying these instructions
and don't sell the design or instructions



1





2





3





4





5





6





7





8





9






10





11




12




13



14



15





2x
3024, 11



1x
2447, 11




2x
2433, 11



1x
4032, 11



1x
973p52, 11




1x
3660, 11



1x
3839b, 11



2x
983, 11



1x
3023, 11




2x
3040, 11



1x
2446, 11



2x
3941, 11



1x
3003, 11



1x
3021, 11



2x
3062b, 11



3x
3069b, 11



2x
4592c02, 11




2x
4531, 11



2x
4588, 11



1x
970c00, 11




1x
4730, 11



1x
981, 11




1x
3937, 11



1x
3004, 11



2x
4276, 11



1x
3039, 11



2x
4595, 11



2x
4590, 11



1x
982, 11



1x
3938, 11



1x
3838, 11




2x
4275, 11



4x
4085b, 11



1x
3020, 11



1x
4871, 11



1x
3795, 11



2x
3034, 11



1x
3934a, 11



1x
3933a, 11



1x
3832, 11




4x
3679, 9




2x
4073, 3




1x
3626b, 3



2x
3023, 3



4x
3680, 3




2x
3957, 3



2x
4073, 17



2x
4740, 17



1x
2466, 19