



Do not connect the red wire. In my case it was +12V and would cause damage to the shield if connected

OCS2 Laser connection schema v1.0

