


The middle pin of the pot is offset slightly in the layout.
In practice the leads of the pot were tending to bend.
The idea of the offset is to create a triangle so that it is less prone to bending.
This is untested.



TITLE: weaver_pot

Document Number:

REV:

Date: 2022-05-11 5:21 PM

Sheet: 1/1