



# Processor and Power Relays


## Feather M0 Addallogger




## Switch 1




## Switch 2




## Switch 3




## Voltage Monitor




## Switch 4



## Switch 5




## Watch Dog Timer




## Sensors





### Panel Temp/Humidity



### IMU




## Inputs/Outputs to I/O Board




## Expansion and Transciever Ports


### Auxillary GPIO Expander




### I2C Multiplexer



### UART Expander



### RS232 Transciever



### RS485 Transciever

