

Regression report

Date: 2024-06-25 Time: 18-59-33

Summary report

Module	Total testcases	Passed	Failed
lldp_interfaces	22	22	0

Testcase Complete Summary: Total: 22, Passed: 22, Failed: 0

Detailed report of lldp_interfaces

Testcase summary: Total: 22, Passed: 22, Failed: 0

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_01.1	Passed	<pre>Input: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.1" } }]</pre>	<pre>Commands: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "state": "merged", "tlv_set": { "ipv4_management_address": "10.1.1.1" } }]</pre>	<pre>Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } }]</pre>	<pre>After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } }]</pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { </pre>	<pre> }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	<pre> "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { </pre>	<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 }], { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	
test_case_01.2	Passed	<pre> Input: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.1" } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module	
				<pre>}, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true</pre>			

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56",</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>		
test_case_02.1	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" } }, { "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	<pre> Commands: [{ "mode": "transmit", "name": "Eth1/5", "state": "merged", "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" } }, { "mode": "receive", "name": "Eth1/6", "state": "merged", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } }] </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } }] </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { </pre>	<pre> "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	<pre> "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	
test_case_02.2	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" } }, { "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" } }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module	
				<pre>}, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true</pre>			

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_03.1	Passed	<pre>Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }]</pre>	<pre>Commands: [{ "enable": null, "med_tlv_select": null, "mode": "transmit", "name": "Eth1/5", "state": "deleted", "tlv_select": null, "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": null }, "vlan_name_tlv": null }]</pre>	<pre>Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }]</pre>	<pre>After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }]</pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2", "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, }, </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	
test_case_03.2	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11",</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_04.1	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" }, }, { "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, }, { "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	<pre> Commands: [{ "med_tlv_select": { "power_management": true }, "mode": "receive", "name": "Eth1/6", "state": "deleted", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true } }] </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true } }] </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", </pre>	<pre> }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": false }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { </pre>	<pre> "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, } </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>	<pre>"name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } },</pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	
test_case_04.2	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }, { "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": false, "max_frame_size": false, "port_vlan_id": false, "power_management": false, "vlan_name": false }, "tlv_set": { "ipv4_management_address": "20.1.1.1", "ipv6_management_address": "20::1" }, "vlan_name_tlv": { "allowed_vlans": "10,15-20", "max_tlv_count": 15 } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }], { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": false }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre data-bbox="1163 147 1415 1534">"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module	
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true,</pre>			

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>		
test_case_05.1	Passed	<pre> Input: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv6_management_address": "30::1" } }] </pre>	<pre> Commands: [{ "name": "Eth1/5", "state": "deleted", "tlv_set": { "ipv6_management_address": "10::1" } }, { "mode": "receive", </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
		<pre> }] </pre>	<pre> "name": "Eth1/5", "state": "replaced", "tlv_set": { "ipv6_management_address": "30::1" } }] </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "10::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "30::1" }, "vlan_name_tlv": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": false }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": false }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } } </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module	
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>	<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>	
test_case_05.2	Passed	<pre>Input: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv6_management_address": "30::1" } }]</pre>	Commands: []	<pre>Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }], { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module	
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true,</pre>			

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre data-bbox="1155 151 1417 1539">"max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>		
test_case_06.1	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv6_management_address": "30::2" } }, { "mode": "transmit", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "40.1.1.1" } }, { "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }] </pre>	<pre> Commands: [{ "med_tlv_select": { "network_policy": false }, "mode": "receive", "name": "Eth1/5", "state": "deleted", "tlv_set": { "ipv6_management_address": "30::1" } }, { "med_tlv_select": { "power_management": false }, "name": "Eth1/6", "state": "deleted" }, { "mode": "transmit", "name": "Eth1/5", "state": "replaced", "tlv_set": { "ipv6_management_address": "30::2" } }, { </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "mode": "transmit", "name": "Eth1/6", "state": "replaced", "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }] </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": false, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "30::1" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": false }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "30::2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", </pre>	<pre> "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { </pre>	<pre> "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { </pre>	<pre> "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } } </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } } </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }], { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }], { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }] </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	
test_case_06.2	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5", "tlv_set": { "ipv6_management_address": "30::2" } }, { "mode": "transmit", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "40.1.1.1" } }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 }] </pre>	<pre> Commands: [] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> After: "Not defined" </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "30::2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true } } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>		
test_case_07.1	Passed	<pre> Input: [{ "mode": "receive", "name": "Eth1/5" }] </pre>	<pre> Commands: [{ "mode": "transmit", "name": "Eth1/5", "state": "deleted", "tlv_set": { "ipv6_management_address": "30::2" } }, { "mode": "receive", "name": "Eth1/5", "state": "replaced" }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv6_management_address": "30::2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }, }, </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", </pre>	<pre> "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_07.2	Passed	<pre> Input: [{ "mode": "receive", "name": "Eth1/5" }] </pre>	<pre> Commands: [] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", </pre>	<pre> After: "Not defined" </pre>	<pre> Error: " </pre>

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>		
test_case_08.1	Passed	<pre> Input: [{ "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }] </pre>	<pre> Commands: [{ "name": "Eth1/6", "state": "deleted" }, { "name": "Eth1/5", "state": "overridden", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "40.1.1.1" }, "vlan_name_tlv": { "allowed_vlans": "30-40", "max_tlv_count": 25 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, } </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>	<pre>"med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	
test_case_08.2	Passed	<pre> Input: [{ "mode": "receive", "name": "Eth1/5", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre data-bbox="1161 147 1512 1536">"vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, },</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, }, },</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>} }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>		
test_case_09.1	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5" }, { "mode": "receive", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "30.1.1.2" } }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 }] </pre>	<pre> Commands: [{ "mode": "receive", "name": "Eth1/5", "state": "deleted", "tlv_set": { "ipv4_management_address": "10.1.1.2" } }, { "mode": "transmit", "name": "Eth1/5", "state": "overridden" }, { "mode": "receive", "name": "Eth1/6", "state": "overridden", "tlv_set": { "ipv4_management_address": "30.1.1.2" } }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "10.1.1.2" }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, } </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { </pre>	<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, </pre>	<pre> "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true } }, </pre>	<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	<pre> "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>	
test_case_09.2	Passed	<pre> Input: [{ "mode": "transmit", "name": "Eth1/5" }, { "mode": "receive", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }] </pre>	Commands: []	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre data-bbox="1161 151 1415 1536">"link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, },</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_10.1	Passed	<pre> Input: [{ "mode": "receive", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }] </pre>	<pre> Commands: [{ "name": "Eth1/5", "state": "deleted" }] </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "mode": "transmit", "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { </pre>	<pre> "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>	<pre> }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", </pre>	<pre> "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { </pre>	<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>	<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>	
test_case_10.2	Passed	<pre>Input: [{ "mode": "receive", "name": "Eth1/6", "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }]</pre>	Commands: []	<pre>Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }]</pre>	After: "Not defined"	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>}, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, }, { "enable": true, "med_tlv_select": { </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }] </pre>		
test_case_11.1	Passed	Input: []	<pre> Commands: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "state": "deleted", "tlv_select": { </pre>	<pre> Before: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, </pre>	<pre> After: [{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	<pre> "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "vlan_name_tlv": { "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "mode": "receive", "name": "Eth1/6", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, { "mode": "receive", "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "tlv_set": { "ipv4_management_address": "30.1.1.2" }, "vlan_name_tlv": { "allowed_vlans": "30,50-60", "max_tlv_count": 5 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	<pre> "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, { "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/10", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } } </pre>	<pre> "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "max_tlv_count": 10 } } </pre>	<pre> "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "network_policy": true, "power_management": true }, "name": "Eth1/14", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "state": "deleted", "tlv_select": { </pre>	<pre> } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "state": "deleted", "tlv_select": { </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
			<pre> "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "state": "deleted", </pre>	<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", </pre>	<pre> "max_tlv_count": 10 }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", </pre>	

Testcase name	Status	User Input	Commands	Before	After	Module
test_case_11.2	Passed	Input: []	<pre> { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "state": "deleted", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> } { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }] </pre>	<pre> "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 }] </pre>	Error: "

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/1", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/2", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/3", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/4", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/5", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/6", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/7", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/8", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/9", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "power_management": true }, "name": "Eth1/10", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/11", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/12", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/13", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/14", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/15", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/16", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/17", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/18", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"name": "Eth1/19", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/20", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/21", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/22", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/23", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>} }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/24", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/25", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/26", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/27", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/28", "tlv_select": {</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/29", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/30", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/31", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/32", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } } }, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>{ "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/33", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/34", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/35", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/36", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/37", "tlv_select": { "link_aggregation": true, "max_frame_size": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/38", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/39", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/40", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/41", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/42", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/43", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/44", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/45", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/46", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true,</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre> "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/47", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/48", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/49", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/50", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, </pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"power_management": true }, "name": "Eth1/51", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/52", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/53", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/54", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/55", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, }, },</pre>		

Testcase name	Status	User Input	Commands	Before	After	Module
				<pre>"vlan_name_tlv": { "max_tlv_count": 10 } }, { "enable": true, "med_tlv_select": { "network_policy": true, "power_management": true }, "name": "Eth1/56", "tlv_select": { "link_aggregation": true, "max_frame_size": true, "port_vlan_id": true, "power_management": true, "vlan_name": true }, "vlan_name_tlv": { "max_tlv_count": 10 } }]</pre>		

Testcase Complete Summary: Total: 22, Passed: 22, Failed: 0