

www.tyrehub.com

ATOZ TYRE HUB PVT. LTD.
3RD EYE RESIDENCY, MOTERA STADIUM
ROAD, MOTERA, AHMEDABAD-380005
GSTIN: 24AARCA0146M1ZJ
State Name: Gujarat Code:24
CIN: U74999GJ2018PTC102806
E-Mail: info@tyrehub.com



Toll Free: 1-800-233-5551

TAX INVOICE

Customer

parth test
parthvdixit89@gmail.com
Mobile number : 7575041221

Invoice Number: TH-202005-29
Invoice Date: 14-May-2020
Order Number: 30609
Order Date: 14-May-2020
Payment Method: Debit card / Credit card / Net
Banking / Wallet

*Keep this invoice for guarantee and warranty purposes.

Product	HSN / SCA	GST	Qty	Price	Discount	Amount
---------	-----------	-----	-----	-------	----------	--------

TVS 90/90-12 54J CONTA550 TBL Tubless Two Wheeler	4011	28%	2	₹781.00		₹1562.00
--	------	-----	---	---------	--	----------

SGST - 14% (OUTPUT) ₹219.00
CGST - 14% (OUTPUT) ₹219.00

*3 years Unconditional warranty from invoice date.
2 years Manufacturing warranty from invoice date.

Vehicle Type : **Activa/Scooter**

Tyre Fitment - FREE	9954	18%		₹0		₹0
Parth Store	9954	18%		₹0.00		₹0.00

SGST - 9% (OUTPUT) ₹0.00
CGST - 9% (OUTPUT) ₹0.00

JK TYRE 205/60 R 16 ELANZO NXT Tubeless Car Tyre	4011	28%	2	₹4570.50		₹9141.00
---	------	-----	---	----------	--	----------

SGST - 14% (OUTPUT) ₹1279.50
CGST - 14% (OUTPUT) ₹1279.50

*3 years Unconditional warranty from invoice date.
2 years Manufacturing warranty from invoice date.

Vehicle Type : **Suv**

Tyre Fitment - FREE	9954	18%		₹0		₹0
----------------------------	------	-----	--	----	--	----

Product	HSN / SCA	GST	Qty	Price	Discount	Amount
Wheel Balancing	9954	18%		₹169.49		₹169.49
Wheel alignment	9954	18%		₹211.86		₹211.86
Car Washing	9954	18%		₹402.54		₹402.54
Parth Store	9954	18%		₹784.00		₹784.00

SGST - 9% (OUTPUT) ₹70.50
CGST - 9% (OUTPUT) ₹70.50

Subtotal	₹13,700.00
Service Charges	₹925.00
Total	₹14,625.00

* Guarantee and Warranty are subject to Tyre Company's terms and condition.
* If consumer is submitting claim for tyre(s) Guarantee or warranty, consumer must wait till Inspector come from the Tyre Company and inspect the tyre.
That tyre replacement it's depend on Tyre Company.
* It is customer's responsibility to call tyre company and register guarantee and warranty.