

**PAYMENT RECEIPT/FITMENT APPOINTMENT**

Company Name Real Industries Ltd. (Formerly known as Real Mazon India Ltd.)
Regd. Office Address DTJ210, Second Floor, DLF Tower B, Jasola District Centre, New Delhi- 110025
CIN U28910DL1995PLC069237
State Address PANDHARKAWADA ROAD, PLOT NO 38, JAISWAL LAYOUT, GAMIN VIBHAG, YAVATMAL, Yavatmal, Maharashtra, 445001
GST No 27AABCR9866P1ZD



Receipt Number	RM1/00001511
Receipt Date	23/06/2025
Receipt Expiry Date	06/10/2025
Order Type	Old
Order of	Front Plate & Rear Plate
Vehicle Number	MH14HJ1164
Chassis Number	H3169
Engine Number	D1859
Vehicle Class	TWO WHEELER MOTOR CYCLE
Vehicle Type	PRIVATE
Owner Name	PREETI WADHWANI
Contact No	9823233878
Fitment Location	RM10-PIMPLE, GOVIND YASHDA CHOCK, BHOSARI BRT ROAD, PIMPLE SAUDAGAR PUNE, Pimpri Chinchwad - MH14-411027 Phone - 9922225965
Fitment Date/Time	08/07/2025 10:30AM
Fitment Location Direction	https://maps.app.goo.gl/wW9fQmvhsDJhxtQS9
Product Amount (Including Fitment Cost)	₹450.000
GST	₹81.000
Total Amount	₹531.000 (Rupees Five Hundred Thirty One Only)

Non transferrable

Subject to MAHARASHTRA Jurisdiction.

Warranty for 5 Years: Applicable as per Rule 50 of CMVR 1989.

Please check your Registration Number with HSRP Affixed on your Vehicle.

Fitment Timing

Morning 10:30 AM to 02:25 PM

Lunch 02:30 PM to 03:00 PM

Evening 03:05 PM to 06:00 PM

- **Customers are requested to come at the set time only to avail better service**
 - **The HSRPs shall be destroyed if the applicant does not arrive for affixation on 3rd appointment or up to 90 days after the first appointment.**
 - **No extra charges will be applied at the authorized affixation center for the HSRP, Rivets, and TLP stickers installation but if any further accessories are required or demanded by the customer for fitment the charges will apply.**
 - **Ensure the vehicle matches the HSRP order details; any mismatch will result in cancellation and forfeiture of the booking amount.**
 - **HSRP will be affixed to the vehicle and cannot be handed over to the owner.**
 - **Avoid using harsh materials, chemicals, or solvents on the HSRP to prevent damage.**
 - **If the old plates on the vehicle are secured with rusted screws, owners are advised to visit a nearby garage to have them removed safely. Do not pressurize our fitters .This will help prevent any potential damage to the vehicle when removing them at the fitment center.**
-

Customer Redressal

Tel: +91-120-6457502, +91-120-6457503

Email: realmazonmhhsrp@outlook.com

Printed On - 23/06/2025 09:08:11 PM