





## V2 Link - WAGO



PoE Passive +28V  
IEEE 802.3af Mode B


RS-422 3MHz



The cables used to connect the device and the power adapter  
reverse the order of the wires.

## USB


PWR\_FLAG → +VBUS  
PWR\_FLAG → Shield  
PWR\_FLAG → Shield




## Power Input / +5V Power

PWR\_FLAG → +28V

+28V ← J106  
WAGO 2601-1101  
← J109  
WAGO 2601-1101



+28V ← J107  
WAGO 2065-100  
← J110  
WAGO 2065-100



+5V ← J108  
WAGO 2065-100  
← J111  
WAGO 2065-100

## Mechanical / Production

PLUG101  
PCB\_Plug\_Horizontal

PLUG102  
PCB\_Plug\_Horizontal

ICON102  
V2

INFO101  
1 2 3 4

INFO102  
Revision

5V ICON101  
+ ICON103


28V ICON104  
+ ICON106

FID101  
FID102  
FID103

ICON105  
ICON107

V2 Link WAGO  
Versio Duo  
External Power Supply

Revision: 2026-01-12  
Id: 1/2  
Sheet: Root  
Updated: 2026-02-25



**Power Supply**  
+5V

Revision: 4  
Id: 5/2  
Sheet: Power +5V  
Updated: 2024-03-28