





4066 has VinH_min of >3.3V, so we need 5V swing

Sheet: /Microprocessor/
File: microprocessor.kicad_sch

Title:

Size: A4

Date:

KiCad E.D.A. kicad (6.99.0-4793-g33d76f63b0-dirty)

Rev:

Id: 2/2