


AZTEEG X5 GT

5-AXIS MOTION CONTROLLER


WIRING DIAGRAM

www.panucatt.com




STEPPER MOTORS


X-AXIS Y-AXIS Z-AXIS EXTR1 EXTR2



VREF pin for digipot current control
Available on SD8825, SD5984 and SD6128



POLOLU STYLE STEPPER DRIVER ORIENTATION




BIGFOOT PROFILE STEPPER DRIVER ORIENTATION

MOTOR POWER INPUT

CONNECT TO MAIN INPUT FOR SINGLE SUPPLY
12-60VDC

MAIN POWER INPUT

PC POWER SUPPLY OR
AC/DC SWITCHING PS
12-30VDC




LOW POWER FANS ONLY

Hardware: V1.0
Document: V1.0

AZTEEG X5 GT

5-AXIS MOTION CONTROLLER

WIRING DIAGRAM



Hardware: V1.0
Document: V1.0