



120 ° sensor motor sequence chart(Forward)

120度电机驱动时序图(正向)



120 ° sensor motor sequence chart(Reversing)

120度电机驱动时序图(反向)



**JY01 drive signal is positive polarity output, please take note when choosing MOS drive circuit and power MOS!**