




v0.1 Bug record:

1. CHG_SB need to have a pull-up resistor
2. No pull-up resistors for SDA and SCL line
3. Need a ESD diode for power key button

| | |
|-----------------------------|---------|
| Sheet: / | |
| File: IOI.kicad_sch | |
| Title: | |
| Size: A4 | Date: |
| KiCad E.D.A. kicad 7.0.9 | Rev: |
| | Id: 1/4 |



Sheet: /Power/
File: Power.kicad_sch


Title:

Size: A4 Date:

Kicad E.D.A. kicad 7.0.9

Rev:

Id: 3/4



Sheet: /interface/
File: interface.kicad_sch

Title:

Size: A4 Date:

Kicad E.D.A. kicad 7.0.9

Rev:

Id: 4/4