

① proportional control

② Design rule checker :
checks for:

- verifies tolerances
- verifies specs

① Clearances - traces too close together

② overlap - overlapping traces

③ Dimension - components too close together
- A trace or pad intersects with a dimension line