


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing facility processed 2 total work orders with a total planned quantity of 1500.0 and 1000.0 completed units. Weighing machine records show 9250.0 finished goods quantity alongside 225.0 rejected quantity and 123.0 scrap quantity. Machine utilization averages varied across stations, with Assembly Station #1 reaching 103.33% utilization.

1. Weekly Production Trends



Production Analysis:

Work order tracking shows a total of 2 work orders consisting of 1 Completed order with 1000.0 planned and 1000.0 completed units, and 1 Planned order with 500.0 planned and 0.0 completed units.


Day	Target	Actual	Status
WO-COMPLETED	1000	1000	On Track
WO-PLANNED	500	0	Below Target

2. Machine Performance (OEE Breakdown)


OEE Overview:

Machine utilization analysis indicates variable performance across the 5 recorded machines. Assembly Station #1, CNC Mill #1, and CNC Lathe #1 met optimal utilization thresholds above 85%, while Auto Assembly Line and CNC Lathe #2 operated below optimal levels at 80.0% and 75.0% respectively.

Line	OEE Score	Status
Assembly Station #1	103.33%	Optimal
Auto Assembly Line	80.0%	Below Target
CNC Lathe #1	88.33%	Optimal
CNC Lathe #2	75.0%	Below Target
CNC Mill #1	97.5%	Optimal



3. Rejection vs. Production Volume by Shift



Shift Efficiency Analysis:


Shift production data recorded a total output of 9250.0 finished goods, with 225.0 rejections and 123.0 scrap units. This results in an overall defect rate of approximately 2.4% based on finished goods and rejections.

Shift	Output	Rejections	Defect Rate
General Shift	9250	225	2.4%

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap distribution across materials indicates HDPE Container 5L is the highest scrap contributor at 30.0 units (25.0%), followed by HDPE Drum 20L at 25.0 units (20.83%), and PET Bottle 500ml at 20.0 units (16.67%).



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate flash defects causing high rejections on HDPE Cap 28mm	HDPE Cap 28mm	Quality Control	2023-12-31
Address low utilization rates on CNC Lathe #2 and Auto Assembly Line	CNC Lathe #2 & Auto Assembly	Production Management	2023-12-31
Resolve neck defects identified in PET Bottle 500ml and 2L lines	PET Bottle Lines	Maintenance	2023-12-31