


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing facility handled 2 total work orders comprising 1,500.0 planned units, with 1,000.0 units completed. Machine utilization across 5 operating machines averaged between 75.0% and 103.3%. Scrap accumulation was led by HDPE Container 5L at 30.0 units out of a total 123.0 scrap units. Total rejections recorded across materials reached 225.0 units, heavily driven by HDPE Cap 28mm at 100.0 rejected units.

1. Weekly Production Trends



Production Analysis:

An analysis of the 2 work orders indicates that 1 work order is fully completed with a planned and completed quantity of 1,000.0 units. The remaining 1 work order is currently in planned status with 500.0 planned units and 0.0 completed units.


Day	Target	Actual	Status
Completed Order	1000.0	1000.0	On Track
Planned Order	500.0	0.0	Below Target

2. Machine Performance (OEE Breakdown)

OEE Overview:

Machine utilization analysis across 5 machines shows peak performance in Machine 6 at 103.3% utilization and Machine 3 at 97.5%. Machine 1 and Machine 8 recorded utilization rates of 88.3% and 80.0% respectively, while Machine 2 underperformed at 75.0%.

Line	OEE Score	Status
Machine 1	88.3%	Optimal
Machine 2	75.0%	Below Target
Machine 3	97.5%	Optimal
Machine 6	103.3%	Optimal
Machine 8	80.0%	Below Target



3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:


Shift-wise weighing machine data is currently unrecorded in the dataset, prompting a focus on aggregate scrap and rejection metrics by material type.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Total scrap across all 7 material codes equals 123.0 units. HDPE Container 5L represents the highest scrap driver at 30.0 units (24.4%), followed by HDPE Drum 20L at 25.0 units (20.3%), and PET Bottle 500ml at 20.0 units (16.3%).



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate high rejection rates for HDPE Cap 28mm	HDPE Cap 28mm	Quality Control	2023-11-15
Perform maintenance check on Machine 2 to improve utilization from 75.0%	Machine 2	Maintenance	2023-11-20
Address root causes of scrap generation for HDPE Container 5L and HDPE Drum 20L	Packaging Line	Production	2023-11-30