


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing facility processed 2 total work orders with a planned quantity of 1500.0 and 1000.0 completed. Across 5 machines, utilization rates ranged from 75.0% to 103.3%. Total production output reached 9250.0 finished goods against 225.0 total rejections and 123.0 scrap quantity.

1. Weekly Production Trends



Production Analysis:

The work order summary shows 1 completed work order with a planned quantity of 1000.0 and a completed quantity of 1000.0, achieving On Track status. Additionally, there is 1 planned work order with 500.0 planned quantity and 0.0 completed quantity, currently evaluated as Below Target.


Day	Target	Actual	Status
Completed	1000	1000	On Track
Planned	500	0	Below Target

2. Machine Performance (OEE Breakdown)


OEE Overview:

Machine utilization analysis across 5 machines indicates varying performance levels. Machine 6 leads with 103.3% utilization, followed by Machine 3 at 97.5% and Machine 1 at 88.3%, all achieving Optimal status. Machine 2 at 75.0% and Machine 8 at 80.0% fall below the optimal threshold.

Line	OEE Score	Status
1	88.3%	Optimal
2	75.0%	Below Target
3	97.5%	Optimal
6	103.3%	Optimal
8	80.0%	Below Target



3. Rejection vs. Production Volume by Shift



Shift Efficiency Analysis:


Shift-wise production data indicates Shift A generated 7800.0 FG quantity with 165.0 rejections and an 2.1% defect rate. Shift B recorded 0.0 FG quantity with 35.0 rejections. Shift C produced 1450.0 FG quantity with 25.0 rejections and a 1.7% defect rate.

Shift	Output	Rejections	Defect Rate
Shift A	7800	165	2.1%
Shift B	0	35	N/A
Shift C	1450	25	1.7%

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap distribution by material shows HDPE Container 5L contributing the highest scrap at 24.4% (30.0 units), followed by HDPE Drum 20L at 20.3% (25.0 units), PET Bottle 500ml at 16.3% (20.0 units), PET Bottle 2L at 14.6% (18.0 units), PET Bottle 1L at 12.2% (15.0 units), PET Jar 250ml at 8.1% (10.0 units), and HDPE Cap 28mm at 4.1% (5.0 units) out of a total 123.0 scrap units.



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate flash defects and high rejections for HDPE Cap 28mm	Material FG005	Quality Control	2023-11-15
Address low utilization and performance on Machine 2	Machine 2	Maintenance	2023-11-20
Review neck defect issues on PET Bottle 500ml and 2L lines	Assembly	Production	2023-11-18