


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing performance report analyzes work orders, machine utilization, and scrap data. Work orders WO202608030001 and WO202608030002 show a planned total of 1500.0 units with 1000.0 units successfully completed. Machine utilization across HUSKY-01 and ABS-01 ranges between 60.0% and 120.0%. Total scrap recorded across materials is 123.0 units.

1. Weekly Production Trends



Production Analysis:

The production analysis evaluates two distinct work orders from the dataset. Work order WO202608030001 remains in Planned status with a planned quantity of 500.0 and 0.0 completed. Work order WO202608030002 has achieved Completed status, fulfilling its planned quantity of 1000.0 units with 1000.0 actual completions.


Day	Target	Actual	Status
WO202608030001	500.0	0.0	Below Target
WO202608030002	1000.0	1000.0	On Track

2. Machine Performance (OEE Breakdown)

OEE Overview:

Machine utilization tracking reveals mixed performance across the monitored equipment. HUSKY-01 recorded utilization rates of 110.0%, 80.0%, and 120.0%, while ABS-01 recorded 115.0%, 90.0%, and 60.0%. Overall performance indicates periods of high efficiency alongside notable drops in capacity utilization.

Line	OEE Score	Status
HUSKY-01	110.0%	Optimal
HUSKY-01	80.0%	Below Target
HUSKY-01	120.0%	Optimal
ABS-01	115.0%	Optimal
ABS-01	90.0%	Optimal
ABS-01	60.0%	Below Target



3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:


Shift-wise weighing machine production data was not provided in the source tables. Consequently, shift tables and metrics cannot be populated at this time.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap distribution analysis identifies HDPE Container 5L as the highest contributor to scrap at 24.4% (30.0 units), followed by HDPE Drum 20L at 20.3% (25.0 units). Total scrap across all listed materials equals 123.0 units.



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate root cause for low utilization drop to 60.0% on ABS-01	ABS-01	Maintenance	2026-07-01
Address high scrap generation (30.0 units) for HDPE Container 5L due to color mismatch	HDPE Container 5L	Quality Control	2026-07-05
Initiate execution of planned work order WO202608030001	HUSKY-01	Production	2026-07-03