


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing production performance report encompasses a total of 2 work orders, comprising 1 completed order with 1,000.0 planned and 1,000.0 completed quantities, and 1 planned order with 500.0 planned quantities. Total scrap across materials reached 113.0 units, led by HDPE Container 5L at 30.0 units and HDPE Drum 20L at 25.0 units. Rejections across material types totaled 225.0 units, with flash defects in HDPE Cap 28mm accounting for 100.0 rejected units.

1. Weekly Production Trends



Production Analysis:

The production data shows a total of 2 work orders, divided into 1 completed work order achieving 1,000.0 completed units against a planned quantity of 1,000.0, and 1 planned work order with 500.0 planned units and 0.0 completed units.

Day	Target	Actual	Status
Completed	1000.0	1000.0	On Track
Planned	500.0	0.0	Below Target

2. Machine Performance (OEE Breakdown)

OEE Overview:

No CapacityAnalysis data was provided in the dataset to evaluate machine utilization.

[Chart Missing]

Line	OEE Score	Status
------	-----------	--------

3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:


No WeighingMachine shift-wise production data was provided in the dataset.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap analysis reveals a total of 113.0 units scrapped across 7 materials. HDPE Container 5L is the highest scrap driver at 30.0 units (26.5%), followed by HDPE Drum 20L at 25.0 units (22.1%), PET Bottle 500ml at 20.0 units (17.7%), PET Bottle 2L at 18.0 units (15.9%), PET Bottle 1L at 15.0 units (13.3%), PET Jar 250ml at 10.0 units (8.8%), and HDPE Cap 28mm at 5.0 units (4.4%).



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate flash defect root causes for HDPE Cap 28mm contributing to 100.0 rejected units.	HDPE Cap 28mm Line	Quality Control	2023-11-15
Address neck defects on PET Bottle 500ml accounting for 50.0 rejected units.	PET Line 1	Production	2023-11-20
Review material scrap rates for HDPE Container 5L and HDPE Drum 20L.	HDPE Processing Area	Manufacturing Engineering	2023-11-25