


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing production report evaluates two work orders with a total planned quantity of 1500.0 and 1000.0 completed units. Capacity analysis across multiple machines shows utilization rates ranging from 60.0% to 120.0%, with several instances of overloaded operations. Scrap generation totals 123.0 across materials, while total rejected quantities equal 225.0 PCS with specific defects identified.

1. Weekly Production Trends



Production Analysis:

Work order analysis shows a total of 2 work orders tracked in the system. Work order WO202608030001 is currently Planned with 500.0 planned units and 0.0 completed units. Work order WO202608030002 is Completed with 1000.0 planned units and 1000.0 completed units, achieving a 100% completion rate for active production.


Day	Target	Actual	Status
WO202608030001	500.0	0.0	Below Target
WO202608030002	1000.0	1000.0	On Track

2. Machine Performance (OEE Breakdown)

OEE Overview:

Capacity analysis records indicate variable machine utilization percentages across 11 entries. Utilization ranges from a low of 60.0% on Machine 1 up to a high of 120.0% on Machine 6. Overload flags are triggered true for Machine 1 (115.0%), Machine 6 (110.0%), and Machine 6 (120.0%), indicating capacity constraints in specific operational cycles.

Line	OEE Score	Status
1	115.0%	Optimal
2	80.0%	Below Target
3	95.0%	Optimal
6	110.0%	Optimal
8	80.0%	Below Target
1	90.0%	Optimal
2	70.0%	Below Target
3	100.0%	Optimal
6	80.0%	Below Target
1	60.0%	Below Target
6	120.0%	Optimal



3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:


The production logs detail output and scrap generated across various material codes and dates, totaling 123.0 KG in scrap quantities and 225.0 PCS in rejected quantities. Primary rejection causes include neck defect, weight variance, color mismatch, crack in jar, flash defect, and wall thickness low.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap analysis by material indicates that HDPE Container 5L is the highest scrap contributor at 24.39% of total scrap, followed by HDPE Drum 20L at 20.33% and PET Bottle 500ml at 16.26%. Lower scrap percentages are recorded for PET Bottle 2L (14.63%), PET Bottle 1L (12.20%), PET Jar 250ml (8.13%), and HDPE Cap 28mm (4.07%).



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate machine overloads on Machine 1 and Machine 6 where utilization exceeded 100%.	Machine Capacity	Production Engineering	2026-08-15
Address high scrap generation in HDPE Container 5L and HDPE Drum 20L lines.	Material Scrap	Quality Control	2026-08-20
Review tooling and parameters to resolve frequent neck defects and flash defects in PET and HDPE products.	Rejection Reasons	Maintenance	2026-08-18