


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The manufacturing facility processed 2 total work orders with a planned quantity of 1500.0 and a completed quantity of 1000.0. Machine utilization across the facility averaged above 88% on key lines, with Machine 6 reaching a peak utilization of 103.33%. Total production yielded 9250.0 FG units alongside 225.0 rejections and 123.0 scrap units. The primary scrap driver was HDPE Container 5L accounting for 30.0 units, while flash defects in HDPE Cap 28mm contributed 100.0 rejected units.

1. Weekly Production Trends



Production Analysis:

The work order summary shows 1 completed work order yielding 1000.0 completed units against a planned quantity of 1000.0, and 1 planned work order with 500.0 planned units and 0.0 completed units. This indicates active scheduling but highlights a backlog on the pending work order. Production flow should be monitored to ensure planned orders transition smoothly into execution without delays.


Day	Target	Actual	Status
WO-Completed	1000	1000	On Track
WO-Planned	500	0	Below Target

2. Machine Performance (OEE Breakdown)


OEE Overview:

Capacity analysis data across 5 machines demonstrates varied utilization rates. Machine 6 and Machine 3 operated at high efficiencies of 103.33% and 97.5% respectively, qualifying as Optimal. Machine 1 performed strongly at 88.33%, while Machine 2 (75.0%) and Machine 8 (80.0%) operated below the 85% threshold, indicating potential bottlenecks or underperformance.

Line	OEE Score	Status
Machine 1	88.33%	Optimal
Machine 2	75.0%	Below Target
Machine 3	97.5%	Optimal
Machine 6	103.33%	Optimal
Machine 8	80.0%	Below Target



3. Rejection vs. Production Volume by Shift



Shift Efficiency Analysis:


Shift-wise performance from the weighing machine data shows Shift A leading with 7800.0 FG units, 165.0 rejections, and a defect rate of 2.1%. Shift B recorded 0.0 FG units with 35.0 rejections, while Shift C produced 1450.0 FG units with 25.0 rejections and a 1.7% defect rate. Shift A's high output is offset by higher absolute rejections, requiring focused quality checks.

Shift	Output	Rejections	Defect Rate
Shift A	7800	165	2.1%
Shift B	0	35	100.0%
Shift C	1450	25	1.7%

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap analysis across 7 distinct material codes reveals a total scrap volume of 123.0 units. HDPE Container 5L is the highest scrap driver at 24.4% of total scrap, followed by HDPE Drum 20L at 20.3% and PET Bottle 500ml at 16.3%. Material-specific process tuning is recommended to mitigate these losses.



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate flash defects causing 100.0 rejections	HDPE Cap 28mm	Quality Control	2023-11-15
Address low utilization and performance bottlenecks	Machine 2 & Machine 8	Maintenance	2023-11-20
Review process parameters to reduce 30.0 scrap units	HDPE Container 5L	Production	2023-11-18