

Manufacturing & Video-Analytics Intelligent Report

"Show machine production and safety violations"

Generated: 2026-09-25 10:31:58

Contents

Executive Summary 3

Machine Production & Capacity Overview 4

Safety Violations & Incidents Analysis 6

Appendix — Data Quality 7


Executive Summary



Matched keywords: machine, production, safety, violation

Machine Production & Capacity Overview

The manufacturing execute system tracks operational output and production metrics across plant machinery. Daily production per machine ranges from 100 to 235 units, with total capacity topping out at 250 units per day. Capacity utilization across active shifts averages 90.91%, reaching peak utilization rates of 120% during high-demand production runs. Work order history demonstrates successful execution, including Work Order 139 completing its full 1,000-unit target on Machine 1, while Work Order 138 was canceled due to bulk cancellation rules.



Data preview — Machine (showing 10 of 10 rows)


MachineCode	Machineld	MachineName	MachineType	ProductionPerDay	Capacity	CompanyId	FGName
ABS-01	1	ABS-01	ABS	100	120	None	None
FM-01	2	FM-01	FM	100	120	None	None
HUSKY-02	3	HUSKY-02	HUSKY	100	120	None	None
ABS-02	4	ABS-02	ABS	110	150	None	None
ABS-03	5	ABS-03	ABS	150	160	None	None
HUSKY-01	6	HUSKY-01	HUSKY	235	250	None	None
FM-02	7	FM-02	FM	100	120	None	None
CNC_001	8	CNC_001	CNC Lathe	Utility Area / Boiler Secti...	Thermopac FX 600	13	415
CONV_001	9	CONV_001	CNC Lathe	Plant-1 / Line-A	LT-20C	13	415

MachineCode	Machineld	MachineName	MachineType	ProductionPerDay	Capacity	CompanyId	FGName
CONV_002	10	CONV_002	CNC Lathe	Plant-1 / Line-A	LT-20C	13	415

Safety Violations & Incidents Analysis

Computer vision models recorded 50 safety incident events and 50 corresponding system alerts from facility cameras. Key non-compliance categories include PPE violations such as 'No-Helmet' and 'No-Vest', alongside tracked items like 'Mask', 'Vest', and 'Shoes'. AI model detection confidence ranges between 0.50 and 0.87, averaging 0.61 across all detected tracks. Incidents are classified under escalation statuses of 'escalated' or 'none', though currently all recorded incidents are marked as inactive.

Safety Violations by Detection Class



Data preview — incidents (showing 10 of 50 rows)

assignment_id	camera_id	camera_name	class_name	confidence	escalation_status	is_active	track_id
6	1	Camera 1	No-Helmet	0.6465809345245361	escalated	False	452
11	1	Camera 1	No-Vest	0.852307140827179	escalated	False	449
6	1	Camera 1	No-Helmet	0.8406550884246826	escalated	False	448
4	1	Camera 1	Mask	0.774753212928772	none	False	447
15	1	Camera 1	Vest	0.6835581660270691	none	False	444
11	1	Camera 1	No-Vest	0.6024695634841919	escalated	False	445
10	1	Camera 1	Shoes	0.5925685167312622	none	False	443
15	1	Camera 1	Vest	0.5093432068824768	none	False	442
10	1	Camera 1	Shoes	0.5971236228942871	none	False	439
15	1	Camera 1	Vest	0.5383949875831604	none	False	440

Appendix — Data Quality

Table	Records	Completeness	Outliers	Score
alerts	50	75.0%	0	Needs review
anomaly_flags	8	8.3%	0	Needs review
incidents	50	100.0%	0	Good
Machine	10	82.5%	0	Fair
MachineFGMapping	39	68.6%	0	Needs review
MachineMaster	28	95.1%	1	Fair
MachineMaterialMapping	8	100.0%	0	Good
ProductionPlanning	8	79.7%	0	Needs review
CapacityAnalysis	11	100.0%	0	Good
FinishedGood	19	100.0%	0	Good
WorkOrder	2	83.3%	0	Fair
WeighingMachine	7	100.0%	0	Good