


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

During the reporting period, only one work order (WO202608030002) was successfully completed, delivering 1,000.0 units out of four planned orders. Capacity analysis across machines showed utilization rates ranging from 60.0% to 120.0%, with Machine 6 reaching a peak of 120.0% utilization. Shift-wise production recorded a total of 9,250.0 units of finished goods, with Shift A contributing the highest output of 7,800.0 units but also incurring 165.0 rejections. Scrap generation totaled 123.0 KG, led by HDPE Container 5L at 30.0 KG, while 225.0 pieces were rejected, primarily due to flash defects in HDPE Caps.

1. Weekly Production Trends



Production Analysis:

The production analysis indicates that out of four work orders, only WO202608030002 was completed, achieving its target of 1,000.0 units. Work order WO202608030001 remains in Planned status with 11,111.0 planned units, while WO202608100002 is in Draft status with 8,888,888.0 planned units. Work order WO202608100001 was cancelled. This highlights a significant gap between planned and completed quantities during this period.


Day	Target	Actual	Status
WO202608030001	111111.0	0.0	Below Target
WO202608030002	1000.0	1000.0	On Track
WO202608100001	2.0	0.0	Below Target
WO202608100002	8888888.0	0.0	Below Target

2. Machine Performance (OEE Breakdown)


OEE Overview:

Capacity analysis reveals varying machine utilization rates. Machine 6 demonstrated high utilization, peaking at 120.0% and 110.0%, indicating potential overload conditions. Machine 1 also operated above optimal levels at 115.0% and 90.0%, but dropped to 60.0% in late June. Machine 3 maintained optimal utilization at 95.0% and 100.0%. Conversely, Machine 2 operated below target at 80.0% and 70.0%, suggesting underutilization.

Line	OEE Score	Status
Machine 1	115.0%	Optimal
Machine 2	80.0%	Below Target
Machine 3	95.0%	Optimal
Machine 6	110.0%	Optimal
Machine 8	80.0%	Below Target
Machine 1	90.0%	Optimal
Machine 2	70.0%	Below Target
Machine 3	100.0%	Optimal
Machine 6	80.0%	Below Target
Machine 1	60.0%	Below Target
Machine 6	120.0%	Optimal



3. Rejection vs. Production Volume by Shift



Shift Efficiency Analysis:


Shift A was the primary driver of production, generating 7,800.0 units of finished goods, but also recorded the highest volume of rejections at 165.0 units (a 2.07% defect rate). Shift C produced 1,450.0 units with 25.0 rejections (1.69% defect rate). Shift B recorded zero finished goods output but registered 35.0 rejections and 25.0 KG of scrap, indicating operational issues or setup trials during this shift. Rejection reasons from the quality log highlight 100.0 pieces of HDPE Cap 28mm rejected due to flash defects and 75.0 pieces of PET Bottles rejected due to neck defects.

Shift	Output	Rejections	Defect Rate
Shift A	7800.0	165.0	2.07%
Shift B	0.0	35.0	100.0%
Shift C	1450.0	25.0	1.69%

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

Scrap analysis shows a total of 123.0 KG of material scrapped. The primary driver is HDPE Container 5L, accounting for 30.0 KG (24.39%), followed by HDPE Drum 20L at 25.0 KG (20.33%) and PET Bottle 500ml at 20.0 KG (16.26%). HDPE materials represent the majority of the scrap weight.



5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Inspect mold and adjust clamping pressure to eliminate flash defects on HDPE Cap 28mm (100.0 PCS rejected).	HDPE Cap Line	Maintenance	2026-08-15
Calibrate blow molding machine parameters to resolve neck defects on PET Bottle 500ml and 2L (75.0 PCS total rejected).	Blow Molding	Quality Assurance	2026-08-18
Review scheduling and distribute load from overloaded Machine 6 (up to 120.0% utilization) to underutilized Machine 2 (70.0% utilization).	Production Planning	Operations	2026-08-20