


PRODUCTION PERFORMANCE & QUALITY REPORT

Facility: Main Manufacturing Plant Reporting Period: Weekly Summary

Executive Summary:

The production summary shows a total planned quantity of 9000001 and a total completed quantity of 1000. The machine utilization is 100% for CNC Lathe #1. The shift-wise production data is not available. The scrap analysis and rejection analysis are also not available.

1. Weekly Production Trends



Production Analysis:

The work order records show that out of 2 products, only 1 has completed quantity greater than 0. The product 'Valve Body Assembly' has completed 1000 units out of a planned 112111 units.


Day	Target	Actual	Status
Industrial Centrifugal Pump	8888890	0	Below Target
Valve Body Assembly	112111	1000	Below Target

2. Machine Performance (OEE Breakdown)

OEE Overview:

The machine utilization is 100% for CNC Lathe #1, which is optimal.

Line	OEE Score	Status
CNC Lathe #1	100.0%	Optimal



3. Rejection vs. Production Volume by Shift

[Chart Missing]

Shift Efficiency Analysis:

No shift-wise production data is available.

Shift	Output	Rejections	Defect Rate
-------	--------	------------	-------------

4. Scrap Analysis & Waste Distribution

Key Scrap Drivers:

No scrap data is available.

[Chart Missing]

5. Corrective Action Plan

Action Item	Target Area	Owner	Deadline
Investigate the cause of zero production for Industrial Centrifugal Pump	Production Line	Production Department	Immediate
Improve production efficiency for Valve Body Assembly	Production Line	Production Department	Short-term