

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-049
Priority	Medium
Completion Date	2026-05-14

Description / Work Detail

Water pressure drop reported in Building B, Units 201 and 203. Tenants noticed slow flow in showers. Plumber consult may be needed. Awaiting Carlos's assessment.