

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-057
Priority	High
Completion Date	2026-05-15

Description / Work Detail

HVAC unit on the third floor of Palomar Building is cycling on and off every few minutes. Tenant in unit 312 reported it this morning. Needs inspection before tomorrow's standup so we have a status to share with the team.