

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-082
Priority	High
Completion Date	2026-05-13

Description / Work Detail

Follow-up inspection confirmed HVAC compressor belt is worn. Parts ordered from Rivera HVAC Supply. Unit operating at reduced capacity in the interim.