

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-039
Priority	Low
Completion Date	2026-05-14

Description / Work Detail

Follow-up on MT-2026-037: plumber visit completed for Unit 4B slow drain. Drain cleared, no further issues reported by tenant.