

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-1252
Priority	Medium
Completion Date	2026-05-15

Description / Work Detail

Water pressure drop in Building B, Units 201 and 203. Plumber consulted - likely sediment buildup in shared line. Scheduled plumber visit for July 21. Medium priority confirmed.