

STAR PROPERTY MANAGEMENT

Southwest Texas Residential Portfolio

MAINTENANCE WORK-ORDER — TICKET REPORT

Ticket Number	MT-2026-1271
Priority	High
Completion Date	(open — no completion date recorded)

Description / Work Detail

Move-out walk completed for Las Palmas Unit 8D following tenant vacancy. Unit requires full turn: carpet has visible staining throughout, kitchen faucet is dripping and needs repair or replacement, and walls show scuff marks requiring touch-up or repaint. Make-Ready Turn record created in Property Operations base with status set to Vacant. Coordinating with team to schedule vendors and get unit rent-ready.